Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-1343/1

Work Order Type: Weatherization Audit Name: 17017UC-1343

CLIENT INFORMATION

Client ID: 17017UC-1343

<u>AGENCY INFORMATION</u>

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:*

Agency Contact:Carlisle, RonWork Phone:Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1997 SITE BUILT HOME

Measures

Measure 1 Fra	ame Repair 18 SQ. FT			Componen	ts			Inspected
Comment								
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	Repair Framing around Windows	Each	18					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
	PLACE PACKAGED HEAT PU			Componen	ts			Inspected
WI				Componen Estimated			Actual	Inspected
WI			Qty	•		Qty		Inspected
Comment	TH A WORKING HEAT PU	UMP	Qty 1	Estimated	<u>'</u>	Qty	Actual	
WI Comment # Material / Labor	TH A WORKING HEAT PU	UMP <i>Unit</i> s		Estimated	<u>'</u>	Qty	Actual	
WI Comment # Material / Labor 10 Unspecified	TH A WORKING HEAT PU	UMP <i>Unit</i> s		Estimated	<u>'</u>	Qty	Actual	
WI Comment # Material / Labor 10 Unspecified	TH A WORKING HEAT PU	UMP <i>Unit</i> s		Estimated	<u>'</u>	Qty	Actual	
WI Comment # Material / Labor 10 Unspecified	TH A WORKING HEAT PU	Units Each	1	Estimated	<u>'</u>		Actual	

		/H Pipe Insulation			Componer	nts			Inspected
C	Comment				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		wrap water pipes							
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail				1		,		
L									
				Measur	e Sub Total:] ,	Sub Total:	
	Measure 4 Atti Comment	ic Ins. R-38			Componer			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1128					
C	Other Detail								
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								

	H Tank Insulation			Componen	ts			Inspecte	
Comment									
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Hot Water Equipment	DHW Tank Insulation	Each	1						
	R-10 minimum-use bubble wrap								
2 Labor	DHW Tank Insulation	Each	1						
Other Detail									
Field Notes:			Measur	e Sub Total:			Sub Total:		
Measure 6 Floo	or Ins. R-19			e Sub Total:	ots FL		L	Inspected	
	or Ins. R-19			L			L	Inspected	
Measure 6 Floo	or Ins. R-19 Description / Comment	Units		Componen		Qty		Inspected Total	
Measure 6 Floo Comment # Material / Labor				Componen Estimated	<u> </u>		Actual		
Measure 6 Floo	Description / Comment Floor Insulation -	Units	Qty	Componen Estimated	<u> </u>		Actual		
Measure 6 Floo Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -	Units	Qty	Componen Estimated	<u> </u>		Actual		
Measure 6 Floo Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -	Units	Qty	Componen Estimated	<u> </u>		Actual		
Measure 6 Floo Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -	<i>Units</i> SqFt	Qty 1128	Componen Estimated	<u> </u>	Qty	Actual		

Measure 7 Stor	Components A4,A1,A5					Inspected		
Comment 5 WIND	OWS							
				Estimated	stimated		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	SqFt	56.25					
	<99 U.Iea. Under 100 UI							
2 Labor	Storm Window	SqFt	56.25					
3 Other	Storm Window	Each Window	5					
	<99 U.I ea Over 100 UI							
Other Detail						1		
			Measure	Sub Total:] ;	Sub Total:	
Field Notes:								
		Work O	rder Grai	nd Total:		Gran	d Total:	